

# Test Report

Sample Name : LED STREET LIGHT

Sample Model : AOK-50WiLB-NV-A3-00-5770-T3

Inspection : Commission test


Manufacturer : AOK Industrial Company Limited

Client : AOK Industrial Company Limited



Guangzhou LCS Compliance Testing Laboratory Ltd.







#### Page 2 of 10 Report No.: LCSC072023003K

### **Test Report**

Client : AOK Industrial Company Limited

: 1/F of 1#Building, East Block of 3/F of Building 1, And 2/F of Building 4, ST George's

Science and Technology Industrial Park, Northside of Xinyu Road, Xiangshan **Address** 

Community, Xianqiao Street Baoan District, 518000 Shenzhen, Guangdong, CHINA

Manufacturer : AOK Industrial Company Limited

: 1/F of 1#Building, East Block of 3/F of Building 1, And 2/F of Building 4, ST George's

**Address** Science and Technology Industrial Park, Northside of Xinyu Road, Xiangshan

Community, Xianqiao Street Baoan District, 518000 Shenzhen, Guangdong, CHINA

The following sample(s) and sample information was/were submitted and identified by/on the behalf of the client:

Sample Name : LED STREET LIGHT

Sample Model : AOK-50WiLB-NV-A3-00-5770-T3

Sample Quantity : 1PC

Sample tested Status : Normal

Sample received Date : Aug.14, 2023

Sample tested Date : Aug.16, 2023

Trade mark

#### Test result information:

Test item : 3G Vibration Test

Test standard ANSI C136.31-2018

Guangzhou LCS Compliance Testing Laboratory Ltd.

Scan code to check authenticity

: See the text Test result

awang-Hu Sound chen Edited by Guang Hu Checked by Sound Chen Approved by Kizard Zhang

Aug.21, 2023 Aug.21, 2023 Aug.21, 2023



Add: No 44-1, Qianfeng North Road, Shiqi, Panyu District, Guangzhou, Guangdong, China Tel: +(86) 020-39166689 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com



# Test Report

#### Revise Record

1		Revise Record		
Report version	Issued date	Revision times	Revised content	Valid version
LCSC072023003K	Aug.21, 2023	1	Original Report	Valid
四岭测度	(情)	五绘测段化		可绘测股份
LCS Testing	Tay.	LCS Testing Le	15	CS Testing Lab
工讯位测照性	工语检测图	份 Lab	工訊位测程份	立语位
Los Testi	Tea Los Testi	1	LosTesti	Los Tes
	-155			p. 12-13
LCS Testing	Lap	医 tind测度的	0 1	用位测度价 STesting Lab
LCS Tes		VST LCS TE	(Si	05 100



Guangzhou LCS Compliance Testing Laboratory Ltd.

Add: No 44-1, Qianfeng North Road, Shiqi, Panyu District, Guangzhou, Guangdong, China
Tel: +(86) 020-39166689 | E-mail: webmaster@lcs-cert.com | Web: www.lcs-cert.com
Scan code to check authenticity





### **Test Report**

#### **Test Item: 3G Vibration Test**

1) Environment conditions:

Temperature: 23.5 °C Humidity: 53%RH

#### 2) Tested Sample:

Sample No.	Sample Name	Sample Model	Sample Quantity	Sample Description
C072023003-001	LED STREET LIGHT	AOK-50WiLB-NV-A3- 00-5770-T3	1PC	Normal

3) Reference Basis: ANSI C136.31-2018

4) Test Condition:

1. Secure to the console and secure;

2. Resonance search vibration test:

a) Frequency(Hz): 2-30;

b) Acceleration(G): 0.2;

c) Swept rate(Oct/min): 1;

d) Test axial: X, Y, Z.

3. Fixed Vibration:

a) Frequency(Hz): X-29.96Hz, Y-(There is no resonance point, take 30.0Hz)Hz, Z-27.90Hz;

b) Acceleration(G): 3;

c) Test cycle(Times): 100000;

4. Sample test condition: Non-Operation.

#### 5) Test Equipment:

Sequence	Equipment Name	Equipment No.	Valid Date to
1	Vibration tester	GLCS-S-177	Aug.13, 2024

#### 6) Test Results:

Sample No.	Test Result	
C072023003-001	After the test, the sample appearance has no visual damage, no abnormal sound appears inside the shaking sample. The sample lit up normally.	







#### Sample Photo before the Test:



**Appearance** 




Report No.: LCSC072023003K

Lit up inspection

#### Sample Photo during the Test:



X axis



Y axis



Z axis







#### Sample Photo after the Test:



Appearance Inspection-Front



Appearance Inspection-Back



Lit up inspection


































































#### **NOTES:**

- 1. The report be without test report seal is considered as INVALID.
- 2. The content of reports cannot be copied without written consent of lab.
- 3. The report will be invalid without signature of testing person, review person and approved person.
- 4. Report will be invalid if altered.
- 5. If there is any objection to the test report, it should be submitted to the lab within 15 days. Otherwise, objection invalid.
- 6. Lab is responsible to the testing samples only.
- 7. The report is only for use of internal by customer or scientific research.
- 8. The applicant and manufacturer's information, product name, model, trademark and other information in this report are provided by the applicant, and the laboratory is not responsible for verifying their authenticity.

Lab Address: No 44-1, Qianfeng North Road, Shiqi, Panyu District, Guangzhou, Guangdong, China

Tel: 86-020-39166689 P.C: 511450





